FIELD INSPECTION REPORT

Date of	Inspection : /	0-12-2020	District: Darbt auge		
Division: Derblanes - 9			Langth (km)		
Name o			i prarame charapati	to baras	
	rrogramme:	MAINTENANCE	+	la fall.	
Packago			Road Id No.:		
Status of the Project: Ongoing/Completed Work is a case of: New Connectivity//			d/Under Maintenance		
and the second second				7 95x)	
Sl. No.		Parameters to) be checked	Remarks	
1.	Payement				
a) —	Road Junction condition			S/U	
b)	Condition of Surfacing			-S/U	
. c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Draina	gc			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
-4.	Compliance History				
a)	Status of ATR's & any others			NO	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME: Speel Show me Akun DESIGNATION: ASSI. Engineer.

Muni 10.12.2020 (Signature)