		And the second section is a second section of the second section of the second section is a second section of
	FIELD INSPECTION REPORT	
of Inspection : 13/12/2 o	District: Siwan	
vision: Mahrajganj Length(KM):		
	MAINTENANCE GITSIN &	
	Ongoing/Completed/Under Maintenance	!
		ntenance
	ameters to be Checked	Remarks
		S/W
		s/y/
		S/W
		S/½°
Whether free from defects such as visible cracks, exposed aggregates in case of CC pavement.		Yes/No
Contraction Joints provided or not (CC Pavement)		Yes/No
Compaction of flank/slope & raincuts if any		yes/N o y
Cross Drainage		
Condition of head walls in Hume pipe culverts including its painting		≴/SRI/\v∫
Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
Condition of railings/slab/approach for Bridges		-S/SRI/U
Road Furniture		·
	**	Yes/No
Compliance History		
tatus of ATR's & any other	rs	No
	of Inspection: 13/12/2 o n: Mahrajganj Of the Road: To 3 - e/Programme: e No.: MR-N/19-20Mal Of the Project: a case of: Par Pavement Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defect case of CC pavement. Contraction Joints provide Compaction of flank/slope Cross Drainage Condition of head walls in Condition of Abutment & V Condition of railings/slab/a Road Furniture Whether sign boards/informationes/Pavement road man Compliance History	Inspection: 13/12/2 o District: Siwan In: Mahrajganj In:

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

DESIGNATION:

ΑE

(Signature)

MANISH KUMAR OJHA (J.E.)