FIELD INSPECTION REPORT

Modhepura Date of Inspection : District: 10/12/220 Division: Length (km): Madhe pura 0.880 km BhairePatti via Bariyahi Maharto Bariyahi Mushani Name of the Road: MAINTENANCE Scheme/Programme: Package No.: Road Id No .: Ongoing/Completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: rameters to be ch Payament Road Junction condition a) SAU b) Condition of Surfacing ₩8/U Riding Quality c) _S/U d) Road Camber ~8/U Whether free from defects such as visible cracks, exposed e) Yes/No aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) Yes/No g) Compaction of flank/slope & raincuts if any Yes/No Cross Drainage 2. Condition of head walls in Hume pipe culverts including its painting S/SRI/U a) b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U c) Condition of railings/slab/approach for Bridges _S/SRI/U Road Furniture 3. Whether sign boards/informatory/cautionary Board/km & 200m Yes/No a) stones/Pavement road markings are provided and maintained

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) 5 #

NA

NAME: Ajoy- Cunar

Compliance History

Status of ATR's & any others