## FIELD INSPECTION REPORT

Date of	Inspection: 1,3)	12/2020	District: Nalanda.		
Division: Oh . 1			Length (km): 1.60 K. M.		
Name of	Tthe Road: Sout	a-Alipuz R	and (SH-78) To Daziyar	ur South	
Scheme	Programme: M	AINTENANCE	NABARD.		
Packago			Road Id No.:		
			/Under Maintenance		
Work is	a case of: No	w-Connectivity/U	lp_gradation/ Maintenance	and the second second	
Sl. No.	Parameters to be checked Remarks				
1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's &	any others		-No	

Overall Rating

Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mukesh Yadau.

DESIGNATION: J.E.