## FIELD INSPECTION REPORT

| Date of Inspection: 08/12/2020   |  |   | District: BHO             | SPUR             |                |  |
|--|--|---|---------------------------|------------------|----------------|--|
| DIVIDATE : noisivid  |  |   | Length (km): 0 '          | 035 K            | mi             |  |
|  |  | air of Damage   | bookge near Sul           | tanper           | z village an   |  |
|  | Programme:   | MAINTENANCE   | *                         |                  |                |  |
| Package No.:   |  |   | Road Id No.: 104          | Vo.: 10401708050 |                |  |
|  |  |   | Under Maintenance Lout of |                  |                |  |
| STATE OF STA |  |   | Jp gradation/ Maintenan   | ce (M            | aintenance     |  |
| Sl. No.  |  | Parameters to   | be checked                |                  | Remarks        |  |
| 1.   | Payement   |   |                           |                  |                |  |
| a)   | Road Junction  | Road Junction condition                                   |                           |                  |                |  |
| b)   | Condition of Surfacing   |   |                           |                  | S/U<br>S/U     |  |
| c)   | Riding Quality   |   |                           |                  |                |  |
| d)   | Road Camber  |   |                           |                  | S/U<br>S/U     |  |
| · e)   | Whether free   | Whether free from defects such as visible cracks, exposed |                           |                  |                |  |
|  | aggregates III   | aggregates in case of CC Pavement.                        |                           |                  |                |  |
| . 1)   | Contraction Joints provided or not (CC Pavement)   |   |                           | Yes/No           |                |  |
| g)   | Compaction of flank/slope & raincuts if any  |   |                           | Yes/No           |                |  |
| 2.   | Cross Drainage   |   |                           |                  | Experience     |  |
| a)   | Condition of head walls in Hume pipe culverts including its painting S/SRI/I   |   |                           |                  | C/CDIA         |  |
| (b)  | Condition of Abutment & Wing walls, Slab in RCC culverts   |   |                           |                  | S/SRI/U        |  |
| c)   | Condition of railings/slab/approach for Bridges  |   |                           | S/SRI/U          |                |  |
| 3.   | Road Furniture   |   |                           | S/SRI/U          |                |  |
| (a)  | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained |   |                           |                  | Yes/No         |  |
| 4.   | Compliance   | History   |                           | MISAS SA         | ILE CONTRACTOR |  |
| a)   | Status of ATI  | R's & any others  |                           |                  |                |  |
| Overall  | Rating :   | Satisfactory (S)  |                           |                  |                |  |
|  |  | Satisfactory but  | requires Improvement      | (SRI)            |                |  |
|  | 1 2  | Unsatisfactory (  | U)                        | ,,,,,            |                |  |
|  |  |   |                           |                  |                |  |

Scanned by CamScanner

(Signature)