## FIELD INSPECTION REPORT

Date of I	inspection:	3/12/2020		Tamui'	
Division: James			Length (km): 2.30 KM		
Name of		as abandh road	Musaha	nitola to	Manyo bander
Scheme/	Programme:	MAINTENANCE		0000	
Package			Road Id No.		1103164
		Ongoing/Completed/U			
	a case of:	New Connectivity/Up	gradauon N	Taintenance	
ShiNon		New Connectivity of	ekiteeked		Kemarks
	Pavement				and the second
a)	Pavement  Road Junction condition			s/u/	
b)	Condition of Surfacing			s/U/	
c)	Riding Quality			s/U	
d)	Road Camber			_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
<b>建</b> 2篇		A TOTAL PROPERTY OF THE PARTY O			
a)	Condition of head walls in Hume pipe culverts including its painting			ting S/SRA/U	
ь)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U-N	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U M	
	koad tii illi	IC AND THE STATE OF THE STATE O	理》:"我们 "种"。——"如此"。	4	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
	negonijaji irtekl	intory —	Ten San		100 miles
a)	Status of ATR's & any others			NIA	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	W.

(Signature) A.

NAME:

**DESIGNATION:**