FIELD INSPECTION REPORT

Date of I	nspection: 10/12/2020 District: Mn2 after pur		
Division: 2.W.D. East - 2 Muzathrhurlength (km): 1.298 K.M			
Name of	the Road: Lo39 to Dohiban (VR 28)		
	Programme: MAINTENANCE (PMLSY)		
Package No.: Road Id No.:			
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	SAU	
b)	Condition of Surfacing	4810	
c)	Riding Quality	►S/U	
d)	Road Camber	∪S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
Ŋ	Contraction Joints provided or not (CC Pavement) Yes/No		
g)	Compaction of flank/slope & raincuts if any Yes/No		
2.	Compaction of flank/slope & raincuts if any Cross Drainage Yes/No		
a)	Condition of head walls in Hume pipe culverts including its painting 1/A S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts HA S/SRI/U		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	"V"

NAME: Santogh Kumor Panka;

DESIGNATION: Junior Engineer

10/12/2020 J-E (Bochaha).

Scanned with CamScanner