FIELD INSPECTION REPORT

	the second of th	the state of the s	TIME OILL	the second state of the second
Date	of Inspection:	12 12 2020	District:	Darbhang
Division:		Washinga-1	Length(Km):	
Name of Road:			day Ke duke	in se mustin
Scheme/Progrmme:		NH57 Binod yadar Ke dukan se musli Maintenance 4515		
Package No.				
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity (Up and A)		
S No.	Parameters 4 - 1 - 21			
1	Pavement	arameters to be Checck	ed	Remarks
a)	Road Junction cond	Ital:		
b)	Condition of Surfac	incon		S/U U
c)	Riding Quality	ing	Allerto	S/U S
d)	Road Camber	The same and the same of the s	- 48 7	S/U S
	Whather free free			S/U S
e)	aggragates in see	defects such as visible cracks	, exposed	3/0 3
ŋ	185 Bates III case (e of CC Pavement		Yes/No 🌂
g)	Contraction Joints provided or not (CC Pavement) Compaction of flank /slope & raincuts if any			Yes/No N
2	Cross Drainage			Yes/No N
	Condition of head walls in Hume pipe culverts including its			
a)	painting	alls in Hume pipe culverts in	cluding its	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			S/SRI/U NA
c)	Condition of walls, Slabs in RCC culverts			S/SRI/U NA
3	Condition of railing /slabs/ approach for Bridges			3/3/1/0
, ,	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and Yes/No Yes/			Yes/No Yes
3	Complianace l	History		
a)	Status of ATR's & any others			
Rich S	Tight	y outers	• 156.53	
Overal	l Rating:			
		Satisfactory (S)		
		Satisfactory but requires Imp		
		Unsatisfactory (U)	rovement (SRI)	SRI
N	lote: - Son	Unsatisfactory (U) ne Past of Ro	ad flood e	Hected 2 de
ame:			Signature)	fected & de
esignation:			12/12/202 Busture)	
COIKUS	nou:		H 6	