FIELD INSPECTION REPORT

Date of Inspection : /	6.18.20	District: Sade o'	
Division: RND Chaples 2		Length (km): 0.40000	
Name of the Road:	side to	attes tota	
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:		VUnder Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
The same of the sa	The second second	P Browniete remanipunite	

St. No. Paramena strong checked		Remarks
(A-1	Pavement.	ob care
a)	Road Junction condition	- S/U
b)	Condition of Surfacing	
e)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
t)	Contraction Joints provided or not (CC Pavement)	You/No
8)	Compaction of flank/slope & raincuts if any	Yes/No
	C (ca.) Digiting (c	233
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
- 13	Rost Engiture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
244	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating

Satisfactory (S)	Land State
Satisfactory but requires Improvement (SRI)	/
Unsatisfactory (U)	

NAME: .

DESIGNATION:

(Signature), 1612.30

William Bandaha

Bandaha

Bandaha

Bandaha