FIELD INSPECTION REPORT

| W | | Int. 1 A | |
|--------------------------|--|-------------------------|---------|
| Date of Inspection : | 1-12-2020 | District: Nawada | |
| Division: Ras | auli | Length (km): O.S.S c.t | |
| Name of the Road: LC | 149 - 10 har | 1 Path TO Beldrija | 7 |
| Scheme/Programme: | MAINTENANCE ' | | |
| Package No.: B12-2SP-477 | | Road Id No.: 10 SO 270. | 2122 |
| Status of the Project: | Ongoing/Complete | d/Under Maintenance | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| CIPOTO - CONTRACTOR | Parameters to | be checked | Remarks |

| Sl. No. | Parameters to be checked | Remarks | |
|---------|--|---------|--|
| 1, | Pavement | | |
| a) | Road Junction condition | š/U | |
| b) | Condition of Surfacing | š⁄ū | |
| c) | Riding Quality | š/U | |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No | |
| Ŋ | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank/slope & mincuts if any | Yes/No | |
| 2. | Gross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | s/ski/u | |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U | |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U | |
| 3. | Road Furniture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No | |
| 7.4. | Compliance History | | |
| a) | Status of ATR's & any others | No | |

Overall Rating

| Satisfactory (S) | |
|---|------------|
| Satisfactory but requires Improvement (SRI) | SPI |
| Unsatisfactory (U) | The second |

(Signature)

NAME: SHALEN SINHA

DESIGNATION: JE ROH

Scanned with CamScanner