FIELD INSPECTION REPORT

Date of Inspection: 16 12 2020			District: Purrea	
Division: Baisi			Length (km): 0.974 KM	
Name of the Road: LO27 PMGSY Charaiga to Bhasiga				
Scheme/Programme: MAINTENANCE Package No.:			Road Id No.:	
Work is a case of: New Connecti		New Connectivity	rity/Up gradation/ Maintenance	
Sl. No.		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			SAU
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No

	c)	Condition of railings/slab/approach for Bridges	3/310/01			
	3.	Road Furniture				
	a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
1	4.	Compliance History				
	a)	Status of ATR's & any others				

Condition of head walls in Hume pipe culverts including its painting

Condition of Abutment & Wing walls, Slab in RCC culverts

Overall Rating

2.

a)

b)

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	V

Sdrish 16.12.2020 (Signature)

S/SRI/U

S/SRI/U2

NAME: Md - Johnson Baitha

Cross Drainage

DESIGNATION: J.E.