FIELD INSPECTION REPORT

				마리가게 되었다. 그 모양 없어요?
Date of Inspection: 06/12/2020 District: Muzadarpur				
Division:				
Division: R.W.D. Muzatlar pur East Dength (km): 3.025 Km Name of the Road: Berheta Chowk Se Bhutone Pracy se Bharaf Sah house:				
Seatement regramme: MAINTENANCE (MMG3 Y)				
Package No.: Road Id No.:				
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked			
1.	Pavement			
a)	Road Junction	condition	S/U .	
b)	Condition of S	urfacing	S/Ų	
c)	Riding Quality		S/U	
d)	Road Camber		JS/U	
c)		from defects such as visible cracks, exposed case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			J
g)	Compaction of flank/slope & raincuts if any			of Floor Jang pue to Flood water 2010.
2.	Cross Drainage			pueto Flood
a)	Condition of l	lead walls in Hume pipe culverts including its painting	S/SRI/U	12 May 28 10 1
b)	Condition of A	Abutment & Wing walls, Slab in RCC culverts	s/sri/u	•
c)	Condition of railings/slab/approach for Bridges S/SRI/U			MA
3.	Rond Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/N			
4.	Compliance l	History	1	<u></u>
a)	Status of ATR's & any others			
Overall Rating: Satisfactory (S)				
		Satisfactory but requires Improvement (SRI)		4 1
		Unsatisfactory (U)	10°	

NAME: Santosh kumar Panka;

DESIGNATION: Twior Engineer.

Scanned with CamScanner

Santoch w. Sanka)
(Signature) T. Ell'2/2020
(Bochoha)