## FIELD INSPECTION REPORT

	Inspection: 1	5/12/2020	District: muzatorpu	<u> </u>	
			Length (km):		
S. C. L.		wasivar Bink	labor shop to Show	tola Tavo	
	Programme:	MAINTENANCE	(mmasy)		
Package			Road Id No.		
	f the Project:	Ongoing/Completed/	gradation/ Maintenance		
	a case of:			Remarks	
Sl. No.		Parameters to be checked			
1.	Pavement				
a)	Road Junction condition			5/0	
b)	Condition of Surfacing			~S/U	
c)	Riding Quality			₩S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
ı)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/ŞRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR	's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAI
Unsatisfactory (U)	, A.

<u>seer</u> 15/12/20

(Signature)

Aepiei si

NAME: Sheo wash Ram

DESIGNATION: 71%

Scanned with CamScanner