FIELD INSPECTION REPORT

Date of Inspection: 17.12-2020 Division: Mulaufantu West.		WATER BUSINESS OF THE RESIDENCE OF THE R	District: Muzaffarfor	
Division		of the chaox &	Length (km): e Porti Pakota NH102	VIO Rate
Scheme	/Programme:	MAINTENANCE	alik best t	
Package	No.:		Road Id No.:	
Status of the Project: Work is a case of:		Ongoing/Completed/Under Meintenance New Connectivity/Up gradation/ Maintenance		
Color Delication	n case of:			
SI. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction	n condition		S S/U
b)	Condition of	Condition of Surfacing		U S/U
c)	Riding Quality			U S/U
d)	Road Camber			S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)		1-Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drain	nge		
a)	Condition of head walls in Hume pipe culverts including its painting		SS/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		5 S/SRI/U	
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		n Yes/No	
4.	Compliance	History		-
a)		'R's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	-

NAME: Titonday kuan.

DESIGNATION: PE