

FIELD INSPECTION REPORT

Date of Inspection :	04/12/2020	District:	East Champaran
Division :	Mohiaganj	Length (km):	4.985
Name of the Road:	Fulwari & Nagdah via Gumbharia		
Scheme/Programme:	MAINTENANCE	mmssy	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finding: 500.00m Road surface damaged due to flood in year (2019-20). Rest surface satisfactory.

flood damage deposit material in FDR MJS in the year (2019-20) (Signature)

NAME: Akhilesh Motasable work done in the year 2019-20. But permanent restoration is required.
DESIGNATION: A.E

Name: Ajay Kumar
DESIGN: J.E

5/12/2020
J.E

5/12/2020
A.E.