FIELD INSPECTION REPORT

Date of In	spection :	16/12/2020	District: Nalanda	
Date of Inspection: 16/12/2020 Division:			Length (km): 1.30 K.H.	
Name of t	he Road: To	14 Proseled Nago	er to kundi	
The second secon	rogramme:	MAINTENANCE		
Package N			Road Id No.:	
	tatus of the Project: Ongoing/Completed/Under Maintenance			
Work is a	ork is a case of: New Connectivity/Up gradation/ Maintenance			
SI. No.		Parameters	to be checked	Remarks
1.	Pavement			1 1 1 1
	Road Junction condition			S/U
a)				S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slope & raincuts if any			Yes/No
g)				
2.	Cross Drainage			S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			3/3/4/0
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.28	Compliance History			1 1 2 1 2
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

(Signature)

NAME: KISRORE KULMER STORE

DESIGNATION: A.E.