FIELD INSPECTION REPORT

		District:
Date of Inspection:	16.12.2020	District: DARBHANGA
Division: BEHIPUR		Length (km): 1.274KM
Name of the Road:	LO26 To Matra	ade backhi
Scheme/Programme:	MAINTENANCE	·
Package No.:		Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Payement	
a)	Road Junction condition	Š/Ų
b)	Condition of Surfacing	Š/U
c)	Riding Quality	Š/U
d)	Road Camber	š/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Š/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	š/sri/u
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	w/h
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(5)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Charles 16/12/2013

(Signature)

NAME: PRAJEEP KUMAR

DESIGNATION: JE

Scanned with CamScanner