

FIELD INSPECTION REPORT

Date of Inspection:	17.12.2020	District:	Hailuoguo
Division:	H1169	Length (km):	1.132 km
Name of the Road:	H1169 Rongli Road 552A9 R111 10220		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-24R-052	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/R
b)	Condition of Surfacing	S/L ✓
c)	Riding Quality	✓ S/R
d)	Road Camber	- S/R
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction joints provided or not (CC Pavement)	- Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in flume pipe culverts including its painting	S/S R/S ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/S R/S N/A
c)	Condition of railing/slab/approach for Bridges	S/S R/S N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 100m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A ✓

Overall Rating

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Rampit Choudhary

Rampit
17.12.2020
(Signature)