FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020. District: Bhagalpur				
Division: Bhagalpur Length (Km): 0.721 km.				
Division: Bhagalpur Length (Km): 0.721 Km. Name of the Road: PND Road bhagalfur Amarbur road to 2 manfur Village.				
Scheme / Programme: I NAWARD				
Package No.: Road Id No.: 20703203011				
Status of the Project: Ongoing / Completed / Under Maintenance				
Work is a case of: New Connectivity / Up gradation / Maintenance				
SL. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	S/U	S	
b)	Condition of Surfacing	S/U	2	
c)	Riding Quality	S/U	2	
d)	Road Camber	S/U	ک	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	74	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	44	
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	ND	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	AL	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	No	
4.	Compliance History			
a)	Status of ATR's & any others	NO		
Overall Rating:				
	Satisfactory (S)			
	Satisfactory but requires Improvement (SRI)	SRI		
	Unsatisfactory (U)			
Called the American States and				

Note: Sign board 4 maintenance board are ruste. Harry are not naintained properly.

NAME: Radhe Ramon Sizel DESIGNATION: Assistant Engineer