

# FIELD INSPECTION REPORT

Date of Inspection : 16/12/2020		District: purnea	
Division : Baisi		Length (km): 0.700 km	
Name of the Road: Dahua Bari Parab tola to Purse Road.			
Scheme/Programme: MAINTENANCE (GRSNY)			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ S/U
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U-NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U-NA
c)	Condition of railings/slab/approach for Bridges		S/SRI/U-NA
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		Yes

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	- SRI -
Unsatisfactory (U)	

\* Maintenance board are not fixed at site.

*haurav kumar*  
16/12/20  
(Signature)

NAME: GAURAV KUMAR

DESIGNATION: ASSISTANT ENGINEER