

FIELD INSPECTION REPORT

Date of Inspection : 7/12/2020	District: East Champaran
Division : Motihari	Length (km): 2.683
Name of the Road: 1063 Jatawa Chichuwaheya ze Muvshhari Toli	
Scheme/Programme: MAINTENANCE	pmcsy
Package No.: BR-11R-583	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N.A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Finding: 1200.0m Surface length damage due to flood 2019-20 & 2020-21 year. Its deposit entered in FDR MIS. Rest surface is satisfactory. damaged surface required repair (Signature) AE
- not restoration.

NAME:

Akhilendra Prasad

DESIGNATION: A.E

Name: Ajay Kumar

DESIGN: JE

08/12/2020