FIELD INSPECTION REPORT

vision:	. 14.	Manuella	Length (km): 10 -7 ch 10	· a.
ime of	the Road: O	may as 1	Lengin (km):	
heme/l	Programme:	MAINTENANCE	District: Keymany Length (km): 0-300 p mis Japan & Ladhaba	
ackage			Road Id No.: 212659618	
			eted/Under Maintenance	
York is	a case of:	New Connectivity/	Jp gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U —
	Condition of Surfacing			S/U -
b)				S/U
c)	Riding Quality			S/U
d)	Road Camber Whether free from defects such as visible cracks, exposed			Yes/No
e)	aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts it any			
2.	Cross Drainage S/SRI/U			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SRI/U			
3.	Road Furniture			
a)	2 000			Yes/No
4.	Compliance History			
a)	Status of ATI	R's & any others		*

(8)	_
Satisfactory (S)	921
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)