## FIELD INSPECTION REPORT

Date of Inspection :	16-12-2020	District: NALAND	A
Division: 14 A Q	TUAL	Length (km): 1.50	71.10
Name of the Road: 6	northering for	To manish Tota Birs	0. 10/0.
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
		a ba chacked	Remarks

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
n)	Rond Junction condition	√S/U
b)	Condition of Surfacing	√S/U
c)	Riding Quality	√S/U
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√8/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	h <b>r</b>
<b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
14.5	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(3R2)
Unsatisfactory (U)	

(Signature)

NAME: muleth 1 cum gry

DESIGNATION: A-E

Scanned with CamScanner