FIELD INSPECTION REPORT

Date of	Inspection: \7	050-12-050	District: Kishangamo		
Division: 1275 hangans -)			Length(km): 6.500 KM		
			Jahus Tola to 43.		
Scheme/Programme: VT 5 H					
Packag			Road Id No.: 3/205 801	857	
Status of the Project: Ongoing		Ongoing/Com	pleted /Under Maintenance		
			Connectivity/ Up gradation / Maintenance		
51. No			rs to be checked	Remarks	
1.	Pavement			S/U	
a)	Road Junction Condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates			Yes/No	
	in case of CC Pavement.			103/140	
f)	Contraction Joints Provided or not (CC Pavement) Yes/N				
g)	Compaction of flank / shop & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its Painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, slab in RCC culverts			S/SRI/U	
c)	Condition of railings/Slab/approach for Bridges			S/SRI/U	
3.	Road Furniture			3/311/0	
a)	Whether sign boards/informatory/cautionary Board/km & 200m			Yes/No	
	stones/Pavement road markings are provided and maintained			163/110	
4.	Compliance History				
a)	Status of ATR's	& any others			

Overall Rating:

Satisfactory(S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory(U)

Praving Raviday.

NAME:

(Signature)