## FIELD INSPECTION REPORT

	A ADDO ANDA		
Date of Inspection: 16.12.2020		District: East champagan	
Division: Aseral		Length (km): 1.065	
	numihar Tola	to To3	A STATE OF STATE
Scheme/Programme:	MAINTENANCI		
Package No.:		Road Id No.: 31708301266	
Status of the Project:		ted/Under Maintenance	
Work is a case of:	WHEN THE PARTY OF	y/Up gradation/ Maintenance	is successful and
SI. No.	Parameters	fo be checked	Remarks
1. Payement			nomina valence
a) Road Junction	Road Junction condition		
	Condition of Surfacing		
9,	Riding Quality		
	Road Camber		
Whether free	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
	Contraction Joints provided or not (CC Pavement)		
g) Compaction of	Compaction of flank/slope & raincuts if any		
2 Cross Draina			
a) Condition of h	Condition of head walls in Hume pipe culverts including its painting		
b) Condition of A	Condition of Abutment & Wing walls, Slab in RCC culverts		
c) Condition of ra	Condition of railings/slab/approach for Bridges		
3. Road Furnitu	rei		
a) Whether sign stones/Paveme	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Maintained Brand Mat Avalable		
	Gompilance History		
a) Status of ATR'	Status of ATR's & any others		

Overall Rating

	The same of the sa
Satisfactory (S)	· yr jan i jan j
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)

NAME: Horrudos Sol

DESIGNATION: AE RUD.

Scanned with CamScanner