Damage Reported in F. D. R

## FIELD INSPECTION REPORT

Date of la	spection :	16-12-2020	District: NALAND	4	
Division: Haman			Length (km): 1.20km		
iame of	the Rond: 60	wat brown Pan	change the chart batter	20 Baran	
Scheme/I	rogramme:	MAINTENANCE			
ackage	(1) 1 전 경영 (1) 1 전 경영 (1) 1 전 (1) 1 T		Road Id No.:		
	the Project:		d/Under Maintenance		
Work is	case of:		Up gradation/ Maintenance		
SI. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Rond Junction condition			√8/U	
b)	Condition of Surfacing			√S/U	
c)	Riding Quality			8/U	
d)	Road Camber			√S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			8/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
<b>a</b> )	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes.			Yes/No	
4.54	Compliance History			4	
a)	Status of ATR's & any others				

Overall Rating :

Satisfactory (S)	91
Satisfactory but requires Improvement (SRI)	Alberta Land
Unsatisfactory (U)	

(Signature)

NAME: much ker Styl

DESIGNATION: A'E

Scanned with CamScanner