## FIELD INSPECTION REPORT

Date of	Inspection:   District : Bhagalpur	>	
Divisio	n: Bhagalpur   Length (Km): 1.0  Abuganj Kunachua Rea  the Road: Ravidas tola to Astandi  Programme:   Muysylscj	d of 6 Mahada	rangti*
Scheme	/Programme: 1 MMW14/501		
Package	10 1110 0 7 7	32130	21
	the Project:   Ongoing / Completed / Under Maintenance		
	a case of:   New Connectivity / Up gradation / Maintenan	će	
		Remarks	
SL. No.	Parameters to be checked		
<u>   .                                    </u>	Pavement	S/U	S
a)	Road Junction condition	S/U	S
b)	Condition of Surfacing  Riding Quality	S/U	3
c)	Road Camber	S/U	5
d) c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	Ho
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	yes
g)	Cpmpaction of flank/slope & raincuts if any	Yes/No	NO
2.	Cross Drainage	1	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	_
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	_
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	<del></del>	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO
4.	Compliance History		
a)	Status of ATR's & any others		
erall Ra	ting		
	Satisfactory (S)		
-1-	Satisfactory but requires Improvement (SRI)		
		SRI	

NAME: Hindry Homed rasatu DESIGNATION: EE

Signature

Scanned with CamScanner