## FIELD INSPECTION REPORT

Date of Inspection: 16 [2]20		District: Rohtash
Division: Salarraron -2		Length (km): 4.75 KM
Name of the Road: Los	i Bandh to bankin	hisipul via braisa chandi roas
Scheme/Programme:		
Package No.:		Road Id No.: 10301001045
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SL No.	Parameters to be checked	Remarks	
1.	Pavement	to Andrew Security Se	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing		
c)	Riding Quality	S/U	
d)	Road Camber	\S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
а)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

Work Stonted.

Moomen (Signatule) 12-way

NAME: Er. Arun Kumar Makto.