FIELD INSPECTION REPORT

| Date of | Date of Inspection: District:- Sitamarh | | | , |
|--|---|--|------------------|----------|
| Division DAVD AV. I. Div. Dennei Longth (km):= 1.2 | | 3 Km. | | |
| | the Road: - LO73 Paktola PM | 1654 To Garas | uni Musalo | nan Tola |
| | Programme:- MAINTENANCE | E | | Bakayri. |
| Package | No.:- BR-328-272. Ro | oad Id No.: 3160 + | 802013 | 100 |
| Status o | f the Project: Ongoing/Completed/U | nder Maintenanc | e | |
| Work is a case of: New Connectivity/Up gradation/ Mainte | | enance | | |
| Sl. No. | Parameters to be check | Parameters to be checked Remark | | |
| 1. | Pavement | | | |
| a) | Road Junction condition | | 910 | |
| b) | Condition of Surfacing | | vs/U | |
| c) | Riding Quality | | -S/U | |
| d) | Road Camber | | √8/Ú | |
| e) | Whether free from defects such as visible cracks | | Ves/No | |
| | exposed aggregates in case of CC Pay | vement | Yes/No | |
| f) | | ntraction Joints provided or not (CC Pavement) | | |
| g) | Compaction of flank/slope & raincuts if any | | Yes/No | |
| 2. | Cross Drainage | | | |
| a) | Condition of head walls in Hume pipe culverts | | ∽S/SRI/U | |
| b) | Condition of Abutments & Wing walls, Slab in RCC culverts | | ∽S/SRI/U | |
| c) | Condition of railing/slab/approach for | or bridges | -S/SRI/U | |
| 3. | Road Furniture | | | |
| a) | Whether sing board/informatory/ca | utionary Board/ | Yes/No V | |
| | Km & 200m stones/Pavement roa | nd marking are | 7 | |
| | provided and maintained | | lar and the same | |
| 4. | Compliance History | | | |
| a) | Status of ATR's & any others | 1 | No | 4 |

Overall Rating :

| Satisfactory (S) | |
|---|-----|
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U) | |

Name:- QAMBABU

DESIGNATION:- E.E. Pubani