FIELD INSPECTION REPORT

	Inspection: 17/12/2020	District: Nalanda	5	
Division: Mark mount		District: Nalandar Length (km): 0.475 Gilanidak pod ke nikat ALU		
	The Rond: Nagaryausa	Gilanidade port k	n'kest	
	Programme: MAINTENANC	ľ.	8-11-US	
Package		Rond Id No.;		
	Water the same of	eted/Under Maintenance		
Sl. No.		y/Up gradation/ Maintenance		
		to be checked	Remarks	
1.	Pavement			
n)	Road Junction condition	U	S/U	
b)	Condition of Surfacing	Uthan	S/U	
c)	Riding Quality	U	S/U	
d)	Road Camber	U	S/U	
e)	Whether free from defects s aggregates in case of CC Paveme	nuch as visible cracks, exposed ent.	Yes/No	
f)	Contraction Joints provided or no	ot (CC Pavement) ND	Yes/No	
g)	Compaction of flank/slope & rain	ncuts if any NO	Yes/No	
2.,	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting ASSRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A S/SRI/U			
c)	Condition of railings/slah/approach for Bridges N/A S/SRI/U			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained /VO			
\$4.5°	Compliance History		**************************************	
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	X
Satisfactory but requires Improvement (SRI)	×
Unsatisfactory (U)	

NAME: RANI KUMAR
DESIGNATION: Sr. Engoneer

Scanned with CamScanner