

FIELD INSPECTION REPORT

Date of Inspection:	17/12/20	District:	Barbhangha
Division:	Barbhangha-1	Length(Km):	
Name of Road:	Purana NH 57 Mahua Per to Hingauli		
Scheme/Programme:	Maintenance (MMGSY, GEN)		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/.Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	S/U U	
c)	Riding Quality	S/U U	
d)	Road Camber	S/U U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S/U S	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NO	
g)	Compaction of flank /slope & raincuts if any	Yes/No NO	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N A	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U N A	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U N A	
3	Road Furniture		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No Y	
3	Compliance History		
a)	Status of ATR's & any others	N	
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)		U	

Some Part of Road damage by flood 2020.

Name:

Designation:

(Signature)

[Signature]
17/12/20
08