FIELD INSPECTION REPORT

Date of	Inspection: 14:12 2020 District: Halanda	
Division	Dengin (km): 1-00	
New John Ben Push & Shahmi lot		
Scheme/Programme: MAINTENANCE M. N. P .4515		
Packag	Road 1d No.:	
Status	Ongoing Completed Onder Maintenance	
	New Connectivity/Op gradation/ Maintenance	
Sl. No. Parameters to be checked		Remarks
1.	Pavement	
a)	Rond Junction condition	√S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	√S/U
d)	Road Camber	√\$/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No 🗸
0	Contraction Joints provided or not (CC Pavement)	Yes/No V
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.1	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRVU
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/skn/n
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/Nov
	Compliance History	* *
	Status of ATR's & any others	1-
	· ·	*

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRE
Unsatisfactory (U)	

NAME: Shiva Prohosh-Sublu DESIGNATION: A.E. Bem