## FIELD INSPECTION REPORT

DATE OF INSPECTION:		DISTRICT	SUPAUL.	
BIVI	SION TRIVENIGANI	LENGTH (Km)	1-617 KM	
NAM	TOTROAD 2- LO49- T 03	to Lalpur (VI	(16)	
SCHEME PROGRAMME MAINTENANCE				
PACKAGENO. BR 35R 131		Road Id No. :	Road Id No. :	
STATUS OF PROJECT: ONNGING/COMPLETED/UNDER MAI			COMPLETED/UNDER MAINTENA	NCE
Worl	Work is a case of : New Connectivity/ Up gradation/Ma			ince
SI. No.	PARAMERERS TO BE CHECKED			EMARKS
1	PAVEMENT		THE RESIDENCE OF STREET	
à	Road junction condition			<b>45/U</b>
b	Condition of Surface			VS/U
c	Riding Quality			~5/U
d	Road Camber			VS/U
e	Whether free fron defects such as visible cracks exposed aggregates in case of CC pavement			Yes/No
f	Construction Joints provided or not (CC Pavement)			Yes/No
g	Compaction of flank/ Slope & Rain cuts if any			¥es/No
2	Cross Drainage			
a	Condition of head walls in Hume pipe culverts including its painting			45/SRI/U
b	Condition of abutment & Wing walls, Slab in RCC culverts			S/SRI/U
С	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Road Furniture			
a	Whether sign boards/informatory/cautionary Board/km & 200m stones/ Pavment road markings are provided and maintained			Yes/No
3	Compliance History	TURKE		Yes/No
a	Status of ATR's & any Others			Tespito
		Satisfactory (S		5

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement

Unsatisfactory (U)

Syrendry Kuma S.DO RWD Chlatafur Name

Signature Signature