FIELD INSPECTION REPORT

Date of	of Inspection :	1111			
FFIVEST	111 4		: Muzaffarpu	/	
Name	of the Road:	23-1 Hurayorp Longth	(km): 1.870	7	
Schem	e/Programme:	as-1 Hurafforpilongth	Vishungours	Madho	
		I WANTENANCE	,		
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
					SL No
1.	Pavement	Parameters to be checked		Remark	
a)		THE COUNTY OF THE PARTY OF THE			
b)	Road Junction condition			SIU	
	Condition of Surfacing			S/U	
c)	Riding Quality			VS/U	
d)	Road Camber			-	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			S/U Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		-		
g)	Compaction of flank/slope & raincuts if any			√Yes/No	
2.	Cross Drainage		Yes/No		
a)					
b)	Condition of Abute as a Number		8/SRI/U		
c)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U		
3.		dition of railings/slab/approach for Bridges		S/SRI/U	
J.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	

Overall Rating

Compliance History

Status of ATR's & any others

4.

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

K ambels

(Signature) RW9

NAME:

DESIGNATION: