Lulgari

FIELD INSPECTION REPORT

Date	fInspection: /	8/12/2020	District: Vaishali	
Divisio	in: Hetipul		Length (km): 1-134	1100 1100 11
AMERICA			The second secon	
ARTE STATES	e/Programme:	MAINTENAN	Road Id No.:	
-	ge No.: of the Project:	Ongoing/Comp	leted/Under Maintenance	Sec.
	s a case of:	The state of the s	ity/Up gradation/ Maintenance	
SL No.]	Parameter	s to be checked	Remarks
1.	Pavement			
:0)	Road Junction condition			✓ S/U
b)	Condition of S	_ S/U		
c)	Riding Quality			V S/U
d)	Road Camber			_ S/U
c)	Whether free aggregates in c	Yes/No		
1)	Contraction Joints provided or not (CC Pavement)			✓ Yes/No
g)	Compaction of flank/slope & raincuts if any			✓ Yes/No
2.	Cross Drainage			Anna Carlo
n)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			28.00
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			✓Yes/No
4.	Compliance Hi	1051		
(t)	Status of ATR's			

Overall Rating

Satisfactory (S)	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

PS 18/12/2020