FIELD INSPECTION REPORT

Date of Inspection: 16.12.2020			District: Munger	
Division: Munger			Length (km): 0.800	
Name	of the Road: 70	3 to Middle sc	hool Bambasa	
Schem	e/Programme :	MAINTENANCE	NABARD	7 <u>19</u> 47 1
Packag			Road Id No.:	
Status	tatus of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/Maintenance				
Sl.No.				Remarks
1	Pavement			
a)	Road Junction condition			√\$/U
b)	Condition of Surfacing			√\$/U
c)	Riding Quality			√ 8/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes / No
f)	Contraction Joints provided or not(CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condititon of Abutment & Wing walls Slab in Rcc culverts - N/A			S/SRI/U
c)	Condition of railings/slab/approach for Bridges — N/A			S/SRI/U
3	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes / No.			Yes / No
4	Compliance Histroy			
a)	Status of ATR's &	& any others		17 19

Overall Rating:

Satisfactory (S)	V.
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	1000 D

(Signature)

NAME:

DESIGNATION:

7