FIELD INSPECTION REPORT

Date	e of Inspection:	7-12-2020	District: Savan	
Divi	Division: RWD Chapea -1		Length (km): 0 500 Km	
	Name of the Road: NH-H Road to		Haverpu lida las	
	me/Programme:	MAINTENANCE	MMGSY(SC)	
	Package No.: Status of the Project: Ongoing/Complete		Road Id No.:	
	is a case of:		Ongoing/Completed/Under Maintenance	
STATE COMM.	NAME OF THE PARTY AND THE PART	New Connectivity/Up gradation/ Maintenance		
SI. No	A STATE OF THE STA	Parameters to be checked		Remarks
1.	Pavement			and the same of th
a)	Road Junction	condition	Ü	S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b) ·	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
3.	Road Furniture			Maria ale a
	Whether sign boards/informatory/cautionary Board/km & 200r stones/Pavement road markings are provided and maintained		Yes/No	
	Sompliance His	ory		n agago y agastra. No sina an Andrea
S	Status of ATR's &	k any others		

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

17-12.2020

(Signature)

Up

mLk

NAME:

DESIGNATION: