(Pa)

FIELD INSPECTION REPORT

17.12-20	District: Muz Hospan
-1	Length (km): 1.468
31 Ambsy Road	To Brisi Bueney.
MAINTENANCE	MMGSY (SC)
	Road Id No.: 315 6 720 1326
Ongoing/Completed/Under Maintenance	
New Connectivity/Up gradation/ Maintenance	
	MAINTENANCE Ongoing/Complete

SL No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	√S/U	
b)	Condition of Surfacing	JS/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	_S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Rakonkumar Rawhan

DESIGNATION: J.E

Scanned with CamScanner

(Signature)