FIELD INSPECTION REPORT

1	IT OF INSPECTION:	DISTRICT	SUPAUL.		
111	VISION TRIVENIGANI	LENGTH (Km)	2.33km		
NA	MEDERDADI- 707- NORTH Baswari Sekh	of PMGSX R Lola Sardan	OAD to - Zola (VR35)		
SCI	CHEME PROGRAMME MAINTENANCE				
PAG	KAGENO. BR 35R 156	Road Id No. :	Road Id No. :		
STA	TUS OF PROJECT:	ONNGING/	ONNGING/COMPLETED/UNDER MAINTENANCE		
	k is a case of :		ectivity/ Up gradation/Majn		
SI.	PARAME	RERS TO BE CHECKED		REMARKS	
1	PAVEMENT				
a	Road junction condition			√\$/U	
b	Condition of Surface			√\$/U	
c	Riding Quality			√S/U	
d	Road Camber			√s/u	
e	Whether free fron defects such as visible cracks exposed aggregates in case of CC pavement			Nes/No	
f	Construction Joints provided or not (CC Pavement)			¥es/No	
g	Compaction of flank/ Slope & Rain cuts if any			yes/No	
2	Cross Drainage				
1	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
	Condition of abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
	Condition of railings/slab/approach for Bridges			√S/SRI/U	
	Road Furniture				
	Whether sign boards/informatory/cautionary Board/ km & 200m stones/ Pavment road markings are provided and maintained			₩es/No	
1	Compliance History				
9	itus of ATR's & any Others			Yes/No	
-	Overall Rating :	Satisfactory (S)		S	
			equires Improvement	-	
				-	
	Unsatisfactory (U)				

Surundrakuman 8-D.O. RWD Chatapur Name

Signature