FIELD INSPECTION REPORT

DALLO	PILL	INSPECTION REPO	DRT	
DATE OF INSPECTION : DIVISION - TRIVENIGANI		DISTRICT	SUPAUL	
		LENGTH (Km)	1.55 KM	L
NAME OF	HOAD: 2048 - TO3 7	To Madlofur	(VRIS)	
SCHEME PROGRAMME MAINTENANCE				
PACKAGENO BR 35R 192		Road Id No. :		
STATUS OF				
Workisac		ONNGING/	ONNGING/COMPLETED/UNDER MAINTENANCE	
SI.	SI. New Connectivity/ Up gradation/Ma			
No. 1 PAVE	No. PARAMERERS TO BE CHECKED			
				REMARK
b Condition of Surface				V5/U
c Riding Quality			VS/U	
d Road Camber			45/U	
e Whethe	Whether free fron defects such as a faith			
6 6	Whether free fron defects such as visible cracks exposed aggregates in case of CC pavement			
Construction Joints provided or not (CC Pavement)				Wes/No
Compaction of flank/ Slope & Rain cuts if any				Yes/No
Cross D				Tes/No
Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
Condition of abutment & Wing walls, Slab in RCC culverts				-
Condition of railings/slab/approach for Bridges				S/SRI/U S/SRI/U
Road Fur	Road Furniture			
Whether s	sign boards/informatory/cautionary are provided and maintained	Board/km & 200m sto	nes/ Pavment road	Yes No
Complian	ce History			
Status of A	TR's & any Others			T v m-
				Yes/No
Overall Ra	ting :	Satisfactory (S)		

Satisfactory (S)

Unsatisfactory (U)

Swrendsa Kumar SBO RWD Chalapar Name

Signature Signature

Satisfactory but requires Improvement