

FIELD INSPECTION REPORT

pirpainti

Date of Inspection:	17/12/2020	District:	Bhagalpur
Division:	Kahalgaoon	Length (km):	
Name of the Road:	MMASY pirpainti Babupur Road to Kharakpur to La.		
Scheme/Programme:	MAINTENANCE MMASY (SC)		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/Maintenance		
Sl. No.	Particulars to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/N	S
b)	Condition of Surfacing	S/N	S
c)	Riding Quality	S/N	S
d)	Road Camber	S/N	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
2.	Cross-drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	N
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	No
4.	Compliance History		
i)	Status of ATR's & any others		No

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Road Furniture not painted. and approx 15m pcc damaged.

(Signature)
17/12/2020

NAME: