## FIELD INSPECTION REPORT

Date of Inspection: 17.12.2020			District: NALANDA		
Division: Biharthorn't			Length (km): 0.740 km		
Name of the Rond: NH-82 Hulaina Road to Basi Millia. Village					
	rogramme:	MAINTENANCE	NOW MR POLLY - 2018		
			Road Id No.:		
Status of the Project: Ongoing/Completed/Under Mai					
Work is a case of: New Connectivity/Up gradation/ Maintenance					
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
n)	Road Junction condition			S/U S	
b)	Condition of Surfacing			45/U 5	
c)	Riding Quality			S/US	
d)	Road Camber			S/U S	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/Noye	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No/4	
g)	Compaction of flank/slope & raincuts if any			Yes/No N [	
2.,	Cross Drainage			,	
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	}
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	)
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
李山	Compliance History			10.5	
a)	Status of ATR's & any others			-	

· Overall Rating

(Signature)

NAME: Rana Barown Kennas Siryh

DESIGNATION: Enerative Expiner.

Scanned with CamScanner

Scanned with CamScanner