

FIELD INSPECTION REPORT

Date of Inspection :	18/12/2020	District:	Samashpur
Division :	Dalsingjara	Length (km):	2.7km
Name of the Road:	NH-28	SE	Morwa bazar lake
Scheme/Programme:	MAINTENANCE		old main
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Completed
Work is a case of:	New Connectivity/Up gradation/ Maintenance		✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

Samir Kumar
(Signature) 18/12/2020

NAME: SAMIR KUMAR

DESIGNATION: E.E