FIELD INSPECTION REPORT

Date of Inspection: 17.12.2020			Dutrict: NALANSA		
Division: Bihauthant			Length (km)1 2-110 km		
		allund-Kotsa			
		MAINTENANC	Road Id No.:		
Package	the Project:	Onnuluu/Comp	leted/Under Maintenance		
	a case of:		ity/Up gradation/ Maintenance		
SL No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			S/U S	
b)	Condition of Surfacing			~S/U ≤	
c)	Riding Quality			4S/U ≤	
d)	Road Camber			'S/U S	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/Nofe	
Ŋ	Contraction Joints provided or not (CC Pavement)			Yes/No 44	
g)	Compaction of flank/slope & raincuts if any			Yes/No J+	
2.,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U J	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
, . . 3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
学到,等人	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	_
Unsatisfactory (U)	-

(Signature)

NAME: Rana Basun Kumas Singh DESIGNATION: ENECUTive Engines.

Scanned with CamScanner