## FIELD INSPECTION REPORT

-			
date of la	nspection: /8/12/2020	District: Nalando	4
ivision:	Harnout	Length (km): 1.046 k	m
	the Road: Ranghad-L	ohanda PUD road	Bhobh
The second secon	rogramme:   MAINTENANCE	, , , , , , , , , , , , , , , , , , ,	
Package		Road Id No.:	
		d/Under Maintenance	
	a case of: New Connectivity/	Up gradation/ Maintenance	
Sl. No.	Parameters to	be checked	Remarks
1.	Pavement		
a)	Road Junction condition	U	S/U
b)	Condition of Surfacing	U	S/U
c)	Riding Quality	<b>&amp;</b> S	S/U
d)	Road Camber	U	S/U
e)	Whether free from defects suc aggregates in case of CC Pavement	ch as visible cracks, exposed l. NA	Yes/No
f)	Contraction Joints provided or not	(CC Pavement) N   A	Yes/No
g)	Compaction of flank/slope & rainc	uts if any NO	Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume p	pipe culverts including its painting	S/ŞRI/U
b)	Condition of Abutment & Wing wa	alls, Slab in RCC culverts NIA	S/SRI/U
c)	Condition of railings/slah/approach		S/SRI/U
3.	Road Furniture		
a)	stones/l'avement road markings are	c provided and maintained	Yes/No
李山。	Compliance History		
a)	Status of ATR's & any others		72.8
	The state of the s		

Overall Rating

Satisfactory (S)	×
Satisfactory but requires Improvement (SRI)	×
Unsatisfactory (U)	V

(Signature) 2/2000

NAME: RAUI KUMAR
DESIGNATION: fr, Engineer

Scanned with CamScanner