FIELD INSPECTION REPORT

Date of Inspection: 18/12/2020			District: Janua	
Division: Janua			Length (km): 0.600 km	
Vame of		ouse of Basul		in to Lake
	Programme:	MAINTENANCE		
Package			Road Id No.: 2080411	8008
Status of the Project: Ongoing/Complete				
	a case of:	New Connectivity/	Up gradation/ Maintenance	Paro estados
SIVNO	A COLUMN TO SERVICE AND ASSESSMENT OF THE PARTY OF THE PA	Paramolers ti	rechecked	Remarks
	Pavement			
a)	Road Junction	condition		_8/Ú
b)	Condition of Surfacing			√8/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Jo	Yes/No		
g)	Compaction of	Yes/No		
70.	e costo paint	ge of the last of		100
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U= /
c)	Condition of railings/slab/approach for Bridges			S/SRI/U N
3	Road Surnifi	ife		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yos/No
# hit		(Store III)		and the second
a)	Status of ATR	's & any others	·	NIA

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Dupte 18/12/2020 275

15/1420 (Signature) 4-C

NAME:

DESIGNATION: