## FIELD INSPECTION REPORT

Date of Inspection: 12-12-20 20		7-12-2080	District: Nalamola	
Division: Haman			Length (km): 3.400	
Name of	the Rond: N	H-30A Pulla T	o Autobiga Ad	
		MAINTENANCE	<del></del>	
Package			Road Id No.:	
	the Project:	Onguing/Completed/	Under Maintenance	
Work is	n case of:	New Connectivity/Up	gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks	
1.	Pavement			
n)	Road Junction condition			√8/U
b)	Condition of Surfacing			S/U~
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.  Yes/No			
n	Contraction Joints provided or not (CC Pavement)  Yes/No			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			√S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained  Yes/No			Yes/No_
<b>*3.</b> F	Compliance History			
a)	Status of ATI	R's & any others		

**Overall Rating** 

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	(0)

(Signature)

NAME: mulet ramor Six

DESIGNATION: A.E

Scanned with CamScanner

N/A