FIELD INSPECTION REPORT

Date of Inspection: 17-12-2080			District: Nalanda	
Division: Haman			Length (km): 0.900	Property of the Control
And the second s			, PWD Rd of mahimachal	100 Sah
Scheme/I	rogramme:	MAINTENANCE		
Package			Road Id No.:	
			ted/Under Maintenance	
			y/Up gradation/ Maintenance to be checked Remarks	
Sl. No.	Parameters to be checked			Vennance
1.	Pavement			
a)	Road Junction condition			√8/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			√S/U
d)	Road Camber			<i>∽</i> 8/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Xes/No
n	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
3	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
43.5	Compliance History			
a)		R's & any others		

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	(SRI)
Unsatisfactory (U)	

(Signature)

NAME: mundle Kor Sigh

DESIGNATION: A.E

Scanned with CamScanner

NIF