## FIELD INSPECTION REPORT

Da	te of Inspection: 18 12.20.20	Division of	
	vision: RWD Dalsinghsarai	District: Samastipur	
		Length(km): 1 • 7	
	201 (0)	, - 1 - 0 - 1 / 110	
		PMC	Y20
	30 77	Road Id No:	
Wo	tus of the Project: Ongoing/Completed/Under	Maintenance	
SI.	ork is a case of: New Connectivity/ Up g	radation/ Maintenance	
No	D		Remarks
1	Pavement		
a)	Road Junction Condition	2	
b)	Condition of Surfacing		S
c)	Riding Quality		2
d)	Road Camber		2
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		HOS
f)	Construction Joint provided or not(CC Pavement)		NO
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		I S
ı)	Condition of head walls in Hume pipe culverts including its painting		S
)	Condition of Abutment & Wing walls, Slab in RCC culverts		
)	Condition of railings/slab/approach for Bridge		HM: H
	Road Furniture		
)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		3
	Compliance History		
)	Status of ATR's & any others		I NO
	Status of ATR's & any others  Overall Rating:	S.R.I	NO

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

Ramel Levra Sto

18 · 12 - 20 20 (Signature)

NAME:

**DESIGNATION:**