FIELD INSPECTION REPORT

THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN		LIPPO MASE ECTION	KEPUKI	
Date of Inspection:		18/12/20101	District	Dallan
Division:		19ahaarea -1	l angth (Vm).	Darbhanga 0710
Name of Road:		Ami DMGSY Bar	ak to Malua M	100
Scheme/Progrmme:		Danagra -1 Length (Km): 0710 Ami pmgsy sarak to Mahua Mandal tola Maintenance		
Package No.		Manitenance		
			Road Id No.	
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
S No.	Parameters to be Checcked			Remarks
1	Pavement			
a)_	Road Junction condition			S/U 5
b)	Condition of Surfacing			S/U \$
<u>c)</u>	Riding Quality			S/U S
<u>d)</u>	Road Camber			S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			yes
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank /slope & raincuts if any			Yes/Nd
2	Cross Drainage			Yes/No Mo
	Cardition of hard small in Warrante and the first of the first			
a)	painting			S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			s/sri/u
c)	Condition of railing /slabs/ approach for Bridges			S/SRI/U YA
3	Road Furniture			
a)	Whethersign boards/informatory/cautionary Board / Km &			Yes
	200m stones/ Pavement_road-markings are provided and—maintained			Yes/No
-				
3	Complianace History			
<u>a)</u>	Status of ATR's & any others			No
Overall Rating:				· · ·
Satisfactory (S)				
Satisfactory but requires Improvement (SRI)				SRI
Ilnsatisfactory (II)				0
	Road	is dangeged due to	foot current	year flood
		De 1	/Signatur	(a)

1:

Name:

Designation:

Scanned by CamScanner